

D. A. STUART COMPANY
MATERIAL SAFETY DATA SHEET

Page 1 of 5

SECTION 1 - CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

CHEMICAL PRODUCT IDENTIFICATION:

PRODUCT NAME : DRAWSOL CW-50
PRODUCT ID NUMBER : 07911.C0 099
PRODUCT CLASS : DRAWING LUBRICANT

MANUFACTURER IDENTIFICATION:

NAME : D. A. STUART COMPANY
ADDRESS : 4580 WEAVER PARKWAY
WARRENVILLE IL
60555
TELEPHONE : 630-393-0833

FOR CHEMICAL EMERGENCY

Spill, leak, fire, exposure, or accident
EMERGENCY CONTACT : CHEMTREC
EMERGENCY TELEPHONE : (800) 424-9300
(703) 527-3887 (INTERNATIONAL)

SECTION 2 - COMPOSITION, INFORMATION ON INGREDIENTS

This product contains no components, present in excess of 0.1%
by weight, which are listed as carcinogens by IARC, NTP, or OSHA.

This product contains no reportable hazardous ingredients. This
Material Safety Data Sheet contains information on good industrial
practice for safe handling of all industrial chemicals.

SECTION 3 - HAZARDS IDENTIFICATION

HEALTH HAZARDS (Acute and Chronic):

ACUTE HEALTH HAZARDS: prolonged or frequent contact may cause skin and
eye irritation. Inhalation of mists/vapors may cause respiratory
irritation.

CHRONIC HEALTH HAZARDS: Not determined for the product as a whole.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY OVEREXPOSURE:

None Determined

ROUTE(S) OF ENTRY:

Inhalation?	Skin?	Ingestion?
Yes	Yes	Possible

SIGNS AND SYMPTOMS OF OVEREXPOSURE:

Possible red and/or itching skin due to overexposure.

D. A. STUART COMPANY
MATERIAL SAFETY DATA SHEET

07911.00 099
DRAWSOL CW-50

SECTION 4 - FIRST AID MEASURES

EYE CONTACT: Flush with water at once for at least 15 minutes, lifting upper and lower lids to ensure even flushing. Seek medical attention.

SKIN CONTACT: Remove contaminated clothing immediately, and wash affected area thoroughly with soap and water. If irritation persists, seek medical attention.

INHALATION: If a person breathes in large amounts of this product, move the exposed person to fresh air at once. If breathing becomes difficult, administer oxygen and seek immediate medical attention.

INGESTION: Rinse mouth immediately. Never give anything to an unconscious person. Do not induce vomiting unless advised by a physician. Seek immediate medical attention.

SECTION 5 - FIRE FIGHTING MEASURES

FIRE AND EXPLOSIVE PROPERTIES:

Flashpoint 350.0 °F COC MIN
Auto-ignition temperature. -N/A
Lower Explosion Limit. . . -N/A
Upper Explosion Limit. . . -N/A

EXTINGUISHING MEDIA:

Dry Chemical, Foam, CO2, Water Fog

UNUSUAL FIRE AND EXPLOSION HAZARDS:

Combustion and/or thermal decomposition can give off hydrogen chloride.

SPECIAL FIRE FIGHTING PROCEDURES:

Clear fire area of unprotected personnel. Do not enter a confined space without a helmet, face-shield, bunker coat, gloves, rubber boots, and a positive pressure MIOH approved self-contained breathing apparatus.

SECTION 6 - ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Persons not wearing proper personal protective equipment as stated in Section 8 should be excluded from area of spill. Extinguish all flames in the vicinity. Dike spill and soak up with inert absorbent material. Place in appropriate containers and affix proper labels.

OTHER PRECAUTIONS:

Use good personal hygiene. For industrial use only.
Avoid breathing mists and vapors. Wear all appropriate personal

D. A. STUART COMPANY
MATERIAL SAFETY DATA SHEET

07911.00 D99
DRAWSOL CW-50

protection equipment at all times.

SECTION 7 - HANDLING AND STORAGE

HANDLING PRECAUTIONS:

Avoid contact with eyes, skin, and clothing. Do not get into eyes, on skin, or clothing. Wash thoroughly after handling. Avoid breathing mist or vapor. Use only with adequate ventilation.

STORAGE REQUIREMENT:

Store in well-ventilated, cool, dry area. Keep containers closed when not in immediate use. Store with compatible materials and equipment.

Store containers closed, away from ignition sources such as open flames. Keep away from extreme temperatures.

SECTION 8 - EXPOSURE CONTROLS, PERSONAL PROTECTION

EYE PROTECTION: Safety Glasses

PROTECTIVE GLOVES: Rubber, Impervious

OTHER PROTECTIVE CLOTHING OR EQUIPMENT:

An eyewash fountain should be located nearby work area at all times for emergency use.

RESPIRATORY PROTECTION (Specify Type):

If ventilation equipment is not sufficient to keep airborne concentrations below exposure limits, a NIOSH approved respirator should be worn.

VENTILATION:

Local Exhaust: Recommended
Mechanical: None Special
Special: None Special
Other: None Special

WORK/HYGENIC PRACTICES:

Use good personal hygiene at all times. Launder soiled clothing before reuse. Wash hands thoroughly before eating or smoking.

SECTION 9 - PHYSICAL AND CHEMICAL PROPERTIES

Physical Appearance : CLEAR, AMBER VISCOUS LIQ.
Odor : SLIGHT ODOR
Physical State : LIQUID
pH : -N/A

D. A. STUART COMPANY
MATERIAL SAFETY DATA SHEET

07911.00 099
DRAWSOL CW-50

Vapor Pressure	:	-N/A
Vapor Density	:	-N/A
Boiling Range	:	Lower - N/A °C Higher - N/A °F
Water Solubility	:	NEGLIGIBLE
Specific Gravity	:	1.260
Evaporation Rate	:	-N/A

SECTION 10 - STABILITY AND REACTIVITY

STABILITY: Stable CONDITIONS TO AVOID: None Known

INCOMPATIBILITY (Materials To Avoid): Strong oxidizing agents, strong acids
HAZARDOUS DECOMPOSITION OR BYPRODUCTS: Oxides of carbon and
hydrogen chloride.

Oil-based products may fume when heated.

HAZARDOUS POLYMERIZATION: Will Not Occur
CONDITIONS TO AVOID: None Known

SECTION 11 - TOXICOLOGICAL INFORMATION

Please refer to Section 3 for information on potential health effects.

SECTION 12 - ECOLOGICAL INFORMATION

Ecological testing has not been conducted on this product.

SECTION 13 - DISPOSAL CONSIDERATIONS

Follow all Federal, State, Local and Corporate Regulations for disposal.
The disposal method and manner practices should be acceptable to good
waste management practices and follow applicable codes and regulations.

SECTION 14 - TRANSPORT INFORMATION

DOT SHIPPING DESCRIPTION:

SECTION 15 - REGULATORY INFORMATION

SARA 311 AND 312 INFORMATION:
This product contains the following substances defined as Hazardous
by OSHA Hazard Communication Standard 29 CFR 1910.1200 (d).

CAS#	Chemical Name	% By Weight
------	---------------	-------------

See Section 2

D. A. STUART COMPANY
MATERIAL SAFETY DATA SHEET

07911.00 D99
DRAWSOL CW-50

SARA 313 INFORMATION:

This product contains NONE of the substances subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR Part 372.

SECTION 16 - OTHER INFORMATION

HAZARDOUS MATERIAL IDENTIFICATION SYSTEM (HMIS) INFORMATION:

Health- 1	Flammability- 1
Reactivity- 1	Personal Protective Equipment- B

PPE "B" = Safety Glasses and Gloves

Prepared by : EHS Department
MSDS Last Revision Date : 01/24/2004
MSDS Print Date : 10/19/2004

THE INFORMATION CONTAINED HEREIN IS BASED ON DATA CONSIDERED ACCURATE BY THE D.A. STUART COMPANY. HOWEVER, NO WARRANTY, EXPRESSED OR IMPLIED, IS GIVEN REGARDING THE ACCURACY OF THESE DATA OR THE RESULTS TO BE OBTAINED BY THE USE THEREOF.